

HARTING Hall Effect Current Sensor HCME 100 A ... 800 A



$I_{PN} = 100\text{ A}, 300\text{ A}, 500\text{ A}, 800\text{ A}$

Identification Part number Drawing Dimensions in mm

HCME 100 A 20 32 010 0101
 HCME 300 A 20 32 030 0101
 HCME 500 A 20 32 050 0101
 HCME 800 A 20 32 080 0101

Connection:
 Metz Type 320
 (PT11504VBBN)

mating connector included
 (Metz SP04504VBNC)

