

| Contents | Page |
|--|------------------|
| Han® Q 2/0 Crimp..... | Han 13.2 |
| Han® Q 2/0 Crimp High Voltage | Han 13.4 |
| Han® Q 2/0 Axial screw | Han 13.6 |
| Han® Q 2/0 Axial screw High Voltage..... | Han 13.8 |
| Han® Q 3/0 Crimp..... | Han 13.10 |
| Han® Q 3/4 Crimp..... | Han 13.12 |
| Han® Q 4/0 Crimp..... | Han 13.15 |
| Han® Q 4/2 Crimp..... | Han 13.17 |
| Han® Q 4/2 Axial screw | Han 13.20 |
| Han® Q 5/0 Quick Lock | Han 13.22 |
| Han® Q 5/0 Crimp..... | Han 13.24 |
| Han® Q 7/0 Crimp..... | Han 13.27 |
| Han® Q 8/0 Quick Lock | Han 13.29 |
| Han® Q 8/0 Crimp..... | Han 13.31 |
| Han® Q 12/0 Crimp/Quick Lock..... | Han 13.34 |
| Han® Q 17/0 Crimp..... | Han 13.37 |
| Han® Q High Density Crimp | Han 13.39 |
| Han® Q Data RJ45 | Han 13.41 |
| Plastic hoods/housings..... | Han 13.43 |
| Metal hoods / housings..... | Han 13.47 |
| EMC hoods/housings | Han 13.50 |
| Accessories | Han 13.53 |