

HARTING Hall Effect Current Sensor HCMR 1000 A with feet



$I_{PN} = 1000 \text{ A}$

Identification	Part number	Drawing	Dimensions in mm
<p>HCMR 1000 A with feet</p> <p>Connection: 4 x screw termination with Faston 6.3 mm x 0.8 mm, 4 x hexagonal nuts included</p>	<p>20 31 100 8101</p>		
<p>HCMR 1000 A</p> <p>Connection: 4 x screw termination with Faston 6.3 mm x 0.8 mm, 4 x hexagonal nuts included</p>	<p>20 31 100 9101</p>		
<p>HCMR 1000 A cable and 3 x HPR with feet</p> <p>Connection: HARTING 3 HPR with male Quintax insert</p>	<p>20 31 100 9103</p>		