





Male connectors, straight


Drawing

Dimensions in mm


Contact dimensions [mm]



Connector dimensions [mm]



Board drillings



Contact positions	x ₁	x ₂
19	37.9	18 x 2 (= 36)
22	43.9	21 x 2 (= 42)
25	49.9	24 x 2 (= 48)