HARTING Residual Current Transformer 10 A





I_{PN} = 10 A

			_
Identification	Part number	Drawing	Dimensions in mm
Residual current transformer 10 A	20 32 001 7101	81	171 - 171 -
			150 4xØ11